

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2021

Submitted Date:

03/22/2021

Document Number:

690102339**FIELD INSPECTION FORM**Loc ID 414518 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	
Chesson, Robert		robert.chesson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414878	WELL	SI	11/01/2019	GW	123-30872	HP FARMS Y 17-04	EG

General Comment:

Engineering Integrity inspection performed on March 17th, 2021 in response to initial form 19 spill report Doc #402629722 received by COGCC on 03/16/2021 that outlines: Laboratory analytical receipt was received, and a historical release was confirmed at the HP Farms Y17-4 flowline closure at the separator. Excavation of impacts will be scheduled.

Details of observations made during this field inspection are located in the flowline section of report. Photo uploaded.

Inspected Facilities

Facility ID: 414878 Type: WELL API Number: 123-30872 Status: SI Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (HP Farms Y 17-04) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402557642 was received on 12/19/2020. No flowline risers were observed at the (PA) wellhead area during this field inspection. Excavation and remediation activities in response to the historical release discovered appear to be nearing completion. No Noble Energy personnel were on site during this field inspection.

As outlined in the CA section of COGCC form 19 doc #402629722;
 Historical impacts were discovered at the riser of the flowline and separator connection during flowline closure. In the vicinity of the separator. Noble conducts AVO inspections of all oil and gas facilities.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102341	Location photo; PA well (view SW)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5382201