

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/18/2021

Submitted Date:

03/23/2021

Document Number:

701101295**FIELD INSPECTION FORM**Loc ID 323864 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Byers, Jim		jbyers@blm.gov	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**General Comment:****COGCC Inspection Report Summary**

Location is in close proximity of Roan Creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area)

During this inspection the following possible compliance issues were observed:

Capacity on tank label is faded and illegible from a distance. (100')

Access road into location is rutted and uneven.

Gas leak at separator.

I contacted Chad Thompkins from Caerus of gas leak and that imediate action was needed. I called by cell phone as soon as I got into cell service area.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road into location is rutted and uneven.		
Corrective Action:	Maintain access road.	Date:	04/10/2021

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No api # on well sign.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not at tank battery.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Capacity on tank label is faded and illegible from a distance. (100')		
Corrective Action:	"Comply with Rule 605.h.(1).C. Tank capacity;(2) Lettering on all new Tanks, and on any reapplied or modified labels, will be legible from a distance of 100 feet."	Date:	06/23/2021

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Gas leak on separator regulator.		
Corrective Action:	Repair gas leak immediately.	Date:	03/19/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			Road ditches not maintained
Gravel						
		Compaction				
Ditches						
Compaction						
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101306	Inspection 701101295 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384043</a>