

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/23/2021

Submitted Date:

03/23/2021

Document Number:

699103274**FIELD INSPECTION FORM**Loc ID 429920 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Grippin, Wyatt	720-415-9544	wgrippin@bonanzacrk.com	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429919	WELL	PR	11/01/2019	OW	123-35968	North Platte P-T-34HZ	PR
429920	LOCATION	AC			-	North Platte P-T-34HZ Pad	AC

General Comment:[This is a follow up to FIRR #402626914. 2 risers are not LO/TO, or marked. Rest of CA's have been corrected.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	#		
Comment:	Risers are not LO/TO or Marked. See attached photos.		
Corrective Action:	Comply with Rule 1102.o	Date:	03/16/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 429919 Type: WELL API Number: 123-35968 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 02/13/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____End Surf Csg Pressure: 0Comment: Well needs updated annual bradenhead test on file. Submit reports per Rule 207.

Corrective Action:

Date:

Facility ID: 429920 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing WellComment: AC

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Tuesday 3/23/21 at approximately 1146hrs, I, Inspector Adam Burns,
Conducted an on-site inspection to FIRR #402626914 at North Platte P-T-34HZ Pad of
Bonanza Creek Energy, at
Location ID # 429920 in Weld County, Colorado.
During this inspection the following possible compliance issues were observed:
Risers are not LO/TO or Marked in multiple spots. Comply with Rule 1102.o. With a
corrective action date of 3/16/21
Well needs updated annual bradenhead test on file. Submit reports per Rule 207.
See attached photos.
A follow up on this site inspection needs to be conducted to ensure the
compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

burnsa

03/23/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699103275	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384312