

**CAERUS PICEANCE LLC**  
**GASAWAY-66S99W /20NESE**  
**Location # 324233**



**Location lack stabilization.**



**CAERUS PICEANCE LLC**  
**GASAWAY-66S99W /20NESE**  
**Location # 324233**



**Location lack stabilization.**



**Location lack stabilization.**



**CAERUS PICEANCE LLC**  
**GASAWAY-66S99W /20NESE**  
**Location # 324233**



**Rutted mud holes on roadway.**



**Rutted mud holes on roadway.**



**CAERUS PICEANCE LLC  
GASAWAY-66S99W /20NESE  
Location # 324233**



**Culvert**

**Coordinates 39.52002 108.46124**



**Culvert needs maintained.**



**CAERUS PICEANCE LLC**  
**GASAWAY-66S99W /20NESE**  
**Location # 324233**



**Sediment moving over shoulder of access road.**



**Sediment moving over shoulder of access road.**



**CAERUS PICEANCE LLC  
GASAWAY-66S99W /20NESE  
Location # 324233**



**Sediment moving over shoulder of access road.**



**Washing erosion of road embankment.**



**CAERUS PICEANCE LLC  
GASAWAY-66S99W /20NESE  
Location # 324233**



**Rutted mud holes on roadway.**



**Rutted mud holes on roadway.**



**CAERUS PICEANCE LLC**  
**GASAWAY-66S99W /20NESE**  
**Location # 324233**



**Rutted mud holes on roadway.**



**Rutted mud holes on roadway.**