

Inspection Photos
Operator: Logos Operating
Facility: 067-05470
Date: 3/16/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of erosional channel forming within the western project area. Channel is approximately 2.5 wide and 2 feet deep.



Photo 3. View of erosional channeling and rilling on the well pad working surface, facing eastward (upslope).



Photo 4. View of erosional channeling within the southeastern project area. Cobble is placed within the erosional channels are full of sediment and not adequate BMPs in this area.



Photo 5. View of reference area comprised of sagebrush shrubland with understory of western wheatgrass and crested wheatgrass.