

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2021

Submitted Date:

03/21/2021

Document Number:

692403240

**FIELD INSPECTION FORM**
 Loc ID 334675 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265798	WELL	PR	07/29/2003	GW	045-09056	ROSE RANCH 11-12B (I10B)	RI
265802	WELL	PR	06/11/2004	GW	045-09060	ROSE RANCH 11-12C (I10B)	RI
265803	WELL	PR	07/26/2003	GW	045-09061	ROSE RANCH 10-10C (I10B)	RI
265814	WELL	PR	07/25/2003	GW	045-09065	ROSE RANCH 10-8C (I10B)	RI
269805	WELL	PR	03/20/2004	GW	045-09412	ROSE RANCH 10-10A (I10B)	RI
269806	WELL	PR	03/20/2004	GW	045-09410	ROSE RANCH 10-9D(I10B)	RI

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

Inspected Facilities				
Facility ID: <u>265798</u>	Type: <u>WELL</u>	API Number: <u>045-09056</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>265802</u>	Type: <u>WELL</u>	API Number: <u>045-09060</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>265803</u>	Type: <u>WELL</u>	API Number: <u>045-09061</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>265814</u>	Type: <u>WELL</u>	API Number: <u>045-09065</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>269805</u>	Type: <u>WELL</u>	API Number: <u>045-09412</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>269806</u>	Type: <u>WELL</u>	API Number: <u>045-09410</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured Pass 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Areas no Longer in use have been Reclaimed. Snow cover prevented detailed assessment of Interim Reclamation areas; though establishment of higher profile species of perennial vegetation are visible above snow cover. Site vegetation would need to be assessed in growing season 2021.

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: <span style="border: 1px solid black; display: inline-block; width: 600px; height: 20px;"></span>						Date <span style="border: 1px solid black; display: inline-block; width: 100px; height: 20px;"></span>
Overall Final Reclamation <span style="border: 1px solid black; display: inline-block; width: 150px; height: 20px;"></span>		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

  

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

  

Comment: Portion of access road between upper Loc#334575 & subject location requires maintenance, sloppy/soft, necessitating 4-wheel drive. Chuff piles (snow removal-snow/gravel/ice/dirt) at location perimeters will need to be dealt with once melt is complete.

Corrective Action: Install or repair required BMPs per Rule 1002.f, stabilizing road & any other seasonal maintenance of BMPs required by 4/30/21, or as soon as weather/ground conditions permit.

Date:  04/30/2021

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692403253	Inspection Photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384833</a>