

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2021

Submitted Date:

03/17/2021

Document Number:

700702440**FIELD INSPECTION FORM**Loc ID 323952 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211343	WELL	PR	10/12/1997	GW	045-07103	FEDERAL RU 14-6	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 3/17/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RU 14-6, at Location # 323952 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. Limited storm water inspection due to snow cover. This location is within or in close proximity to a CPW Density/High Priority Habitat, Black bear, NSO Habitat and Wildlife Management Area.

This location is also within the 317B buffer.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
 2. No evidence of tracking control BMP's
 3. Location and lease road show signs of lack of stabilization/compaction and tracking from pad to lease road is apparent.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:	muddy in areas		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Braden heads have telemetry for monitoring.		

Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	One (1) chemical tank at tank battery in plastic containment, One (1) chemical tank at separators in plastic containment and One (1) chemical tank at well head in plastic containment		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	Two (2) tanks are heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211343	Type:	WELL	API Number:	045-07103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:				Date:					

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Ditches				
Ditches		Culverts				
		Rip Rap				
Berms		Check Dams				

Comment: Limited storm water inspection due to snow cover. This location is within or in close proximity to a CPW Density/High Priority Habitat, Black bear, NSO Habitat and Wildlife Management Area.
This location is also within the 317B buffer.
1. No evidence of tracking control BMP's
2. Location and lease road show signs of lack of stabilization/compaction and tracking from pad to lease road is apparent.

Corrective Action: 1. Install, maintain or provide documentation of post construction management plan or BMP's
2. Install or repair required BMPs

Date: 05/17/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402634243	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5381461
700702444	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5381455