

Inspection Photos

3/25/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334721

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334721



Photo 1: Photo taken from the gully erosion on slopes of the south end of the Location. Operator appears to have placed soils in an effort to repair gully, however, Operator has failed to install required stormwater and erosion control measures to stabilize and protect slopes. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334721



Photo 2: Continued from photo 1. Photo shows that Operator appears to have placed soils in an effort to repair gully, however, Operator has failed to install required stormwater and erosion control measures to stabilize and protect slopes. 6 foot measuring stick for reference.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334721



Photo 3: Continued from photo 2. Photo shows off-location sediment transport and deposition due to erosion degradation and runoff from the Location's slopes.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334721



Photo 4: Photo taken from the gully erosion on slopes of the south end of the Location. Operator appears to have placed soils in an effort to repair gully, however, Operator has failed to install required stormwater and erosion control measures to stabilize and protect slopes. 6 foot measuring stick for reference.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334721



Photo 5: Photo taken from the slope drain outlet for the western-most sediment trap. Operator has installed rip-rap as an outlet; unclear if outlet has been constructed in accordance with good engineering practices in regards to size and installation; additional monitoring will be required to determine if BMP is adequate and in proper functioning condition.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334721



Photo 6: Photo taken from the west end of the drain outlet, facing west. Photo shows hay bale control measure remains in disrepair. Hay bale is considered debris.

