

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Well sign illegible.



Well sign illegible.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Road ditch needs maintained.



Door has fallen off meter shed.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Damaged caution sign on meter shed.



Piece of 1" pipe on the ground behind meter shed.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Label in illegible on buried tank.



Vertical separator

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Junk on location.



Junk on location.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Unused equipment laying against separator.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Door is open on separator.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Open ended 2" unused riser at well



No access for braden.



MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Fence around pit is falling over.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



**Fence post burnt up and fence on eastside
of pit has fallen down.**

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Channel running into pit.



MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Erosion rill down roadway.



Ditch on roadway needs maintained.

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



Sediment moving from roadway onto location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423



MARALEX RESOURCES INC
DRY FORK FEDERAL 1-29
Location ID: 322423

