

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/23/2021

Submitted Date:

03/26/2021

Document Number:

701500021

**FIELD INSPECTION FORM**Loc ID 336462 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	
Boulger, Levin		lboulger@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270161	WELL	SI	10/01/2020	GW	103-10392	ANT HILL UNIT 36-11	SI
270162	WELL	SI	10/01/2020	GW	103-10393	ANT HILL UNIT 36-11BD	SI

**General Comment:**

A follow up inspection of documents:

- 1) FIR 700702090 dated 12-29-2020.

The following compliance issues are uncompleted:

- 1) Debris on location. Photos 1, 2, 7, 8. Complete by 2-3-2021.

Additional compliance issues:

- 1) Stained soil at separator. Photos 5 & 6. Complete by 4-10-2021.
- 2) Chemical label illegible. Photo 10. Complete by 5-26-2021.
- 3) Storm water channeling. Photos 11 to 15. Complete by 5-26-2021.
- 4) Missing "911" on battery sign. Photo 16. Complete by 4-26-2021.

Location is with a CDPHE Reg 42 Limited use &amp; quality area, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, and Rule 309.e.1 Greater sage grouse general habitat management area.

This is a summary of inspection report 701500021.

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical label is illegible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/26/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign at meter building.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on battery sign.

Corrective Action: Install sign to comply with Rule 605.e. Date: 04/26/2021

## Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at separator.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	04/10/2021
Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.	Date:	02/03/2021

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

## Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

## Equipment:

Type: Gas Meter Run	# 2		corrective date
Comment:	Telemetry.		

Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical containers.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenhead access.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 270161 Type: WELL API Number: 103-10392 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production June 2020.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 270162 Type: WELL API Number: 103-10393 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last recorded production June 2020.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Fail					
Gravel		Gravel				
Ditches						
Rip Rap	Fail			Material Handling And Spill Prevention		

Comment: The rip rap is partially washed out in the ditch on the south side of the location. The ditch continues into a retention pond which has a stormwater generated tunnel through the pond berm. Which causes the retention pond incapable of holding water. A stormwater channel passes through the tunnel to the county road located 150' away. The stormwater channel continues into the ditch along the side of the county road.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 05/26/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500022	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387183">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387183</a>