

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2021

Submitted Date:

03/26/2021

Document Number:

695104136**FIELD INSPECTION FORM**Loc ID 334210 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270573	WELL	PR	02/25/2005	GW	071-07946	PARADISE 13-8	PR
289275	WELL	PR	03/22/2008	GW	071-09196	PARADISE 13-8 TR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: PRIME MOVER ON PUMPJACK IS LEAKING, OIL IS RUNNING OFF PUMPJACK BASE ON ONTO SOIL.		
Corrective Action:	COMPLY WITH RULE 606., Conduct maintenance on equipment (REPAIR LEAKS), cleanup stained material and review self inspection processes. THIS IS SECOND NOTICE OF THIS CA.		Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Pump Jack	#		
Comment:	Phone 4: JUMPJACK GEAR BOX IS SATURATED WITH WHAT APPEAR TO BE OIL LEAKING FROM GEAR BOX.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. THIS IS SECOND NOTICE FOR THIS CA.		Date:
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		

Comment:	BOTH ARE PLUMBED TO SURFACE			
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 270573 Type: WELL API Number: 071-07946 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 289275 Type: WELL API Number: 071-09196 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	280371	1140756	

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP., DOC#695102104, CA'S HAVE NOT BEEN ADDRESSED. THIS IS A SECOND NOTICE FOR THESE CORRECTIVE ACTION, IF CA'S ARE NOT ADDRESSED ENFORCEMENT MAY BE CONSIDERED.	beardslt	03/26/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104137	INSP PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387209