

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2021

Submitted Date:

03/26/2021

Document Number:

695104154

FIELD INSPECTION FORM

Loc ID 333680 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273781	WELL	PR	01/01/2020	GW	071-08211	COWBOY 14-5	PR
280358	WELL	PR	12/07/2005	GW	071-08551	COWBOY 14-5 TR	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Phone 3: UNUSED RISER OR BRADENHEAD DOES NOT HAVE VALVE ON TR WELL (I CANNOT DETERMINE IF THIS IS THE BRADENHEAD OR JUST AN UNUSED RISER).		
Corrective Action:	EITHER COMPLY WITH RULE 606 AND REMOVE UNUSED RISER OR COMPLY WITH RULE 341 AND CAP THIS LINE SO BRADENHEAD PRESSURES CAN BE MONITORED.		Date: <u>04/26/2021</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	BOTH PITS		
Corrective Action:			Date: _____

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	ORIGINAL WELL IS PLUMBED TO SURFACE. UNNONE ON TR WELL SEE HOUSEKEEPING FOR CORRECTIVE ACTIONS.		
Corrective Action:			Date: _____
Type: Gas Meter Run	# 2		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date: _____

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Inspected Facilities

Facility ID: 273781 Type: WELL API Number: 071-08211 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 280358 Type: WELL API Number: 071-08551 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	288827	1396601	
	278513	1445874	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104155	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387215