

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2021

Submitted Date:

03/28/2021

Document Number:

688310158

FIELD INSPECTION FORMLoc ID 317000 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 2820 LOGAN DRIVE

City: LOVELAND State: CO Zip: 80538

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Bradley, Sam	970-593-8626	sbradley.impetro@gmail.com	Principal Agent
Quint, Craig		craig.quint@state.co.us	
Gibson, Rick	970-768-6880	rtgibson01@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234305	WELL	SI	10/01/2020	OW	121-06415	BLAKE 1	SI

General Comment:Accident Inspection

Operator contacted inspector at ~8:30 am, Friday, 3/26/2021, about a fire at this well and associated tank battery that had started at ~5 am. According to the operator, a nearby landowner contacted the Last Chance Fire Department, SW Washington County Station 3, sometime after 5 am on 3/26/2021, and they left at ~7 am. The fire was mostly contained between the well deadmen (a small part of the fallow crop field to the the SW and some grass to the NW were also burned). The electric control panel at the pumping unit was burned and on the ground because the post it was attached to was split. The 300 bbl AST crude oil tank was burned with fire coming out of the thief hatch at time of inspection but was considered all but empty by the operator. The partially buried 200 bbl fiberglass, fluid collection tank was burned to the ground level. The tank heater (run by propane) was not turned on. According to the Morgan County REA person, the fuses at the associated power pole at CR L were "sizzled" at 0551 hrs that morning per his computer records and so he was called out. The operator will submit a Form 22 to COGCC and COGCC will fly a drone to further investigate the fire. See attached photos.

Inspected FacilitiesFacility ID: 234305 Type: WELL API Number: 121-06415 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut down due to fire.Corrective Action: Submit Form 22, Accident Report, to COGCC.Date: 03/30/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688310191	Impetro Resources Blake 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387325