

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



Photo #3292 from entrance to location.



Photo #3293 from entrance to location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



**Photo #3295 Location lacks stabilization.**



**Photo #3296 Location lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



**Photo #3297** No form of tracking control at entrance to location.



**Photo #3303** Gully erosion occurring in ditch on East side of access road.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /10NWSE

Location ID: 312690



**Photo #3300 Sediment has migrated on to location and is collecting against tank containment.**