

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2021

Submitted Date:

03/23/2021

Document Number:

701101301

FIELD INSPECTION FORMLoc ID 323864 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Byers, Jim		jbyers@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211035	WELL	SI	03/01/2020	GW	045-06793	GASAWAY (FEDERAL) 6206 (27-1)	SI

General Comment:

Follow up to 3/18/2021 inspection 701101295

Gas leak at separator has been repaired.

ALL OTHER CORRECTIVE ACTIONS FROM the PREVIOUS INSPECTION THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

COGCC Inspection Report Summary

Location is in close proximity of Roan Creek and in a High Priority Habitat Area. (Elk Migration Corridor, Elk Winter Concentration Area, Mule Deer Winter Concentration Area)

During this inspection the following possible compliance issues were observed:

Capacity on tank label is faded and illegible from a distance. (100')

Access road into location is rutted and uneven.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Access road into location is rutted and uneven.		
Corrective Action	Maintain access road.	Date:	04/10/2021

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Capacity on tank label is faded and illegible from a distance. (100')		
Corrective Action:	"Comply with Rule 605.h. (1).C. Tank capacity; (2) Lettering on all new Tanks, and on any reapplied or modified labels, will be legible from a distance of 100 feet."	Date:	06/23/2021

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		

Comment:	Braden head accessible for monitoring.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	Gas leak at separator has been repaired.			
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	211035	Type:	WELL	API Number:	045-06793	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Producing well								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction	Pass					
		Compaction				
Gravel	Pass					
		Gravel				
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402637202	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384097
701101309	Inspection 701101301 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384095