

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/23/2021

Submitted Date:

03/23/2021

Document Number:

700702462

FIELD INSPECTION FORM

Loc ID 334617	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, COGCC		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211150	WELL	TA	02/01/2018	GW	045-06909	PARKER RANCH 15-8	TA
259138	WELL	PR	06/01/2002	GW	045-07690	ROSE RANCH 14-5 (H15)	PR
259139	WELL	PR	06/01/2002	GW	045-07691	ANDREW 15-1 (H15)	PR
259140	WELL	PR	06/01/2002	GW	045-07692	ROSE RANCH 15-10 (H15)	PR
259141	WELL	SI	11/01/2020	GW	045-07693	ROSE RANCH 15-7 (H15)	SI

General Comment:**COGCC Inspection Report Summary**

On Tuesday 3/23/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus H15, at Location # 334617 in Garfield county Colorado.

While there, I observed normal production operations. I also did not drive into location because of the evidence of lack of stabilization. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
 2. Location and access road show signs of lack of stabilization/compaction
 3. Evidence of tracking onto County Road 319 from access road and possibly from location as that there is no evidence of tracking controls as stated in the provided document (BMP's for sediment tracking controls) from the operator.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	Location and access road show signs of lack of stabilization/compaction Evidence of tracking onto County Road 319 from access road and possibly from location as that there is no evidence of tracking controls as stated in the provided document (BMP's for sediment tracking controls) from the operator. SEE STORMWATER		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1. Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities

Facility ID: 211150 Type: WELL API Number: 045-06909 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: last MIT was done 11/13/2018

Corrective Action: _____ Date: _____

Facility ID: 259138 Type: WELL API Number: 045-07690 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 259139 Type: WELL API Number: 045-07691 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 259140 Type: WELL API Number: 045-07692 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 259141 Type: WELL API Number: 045-07693 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: last produced 10/1/2020

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Compaction	Fail			
Berms						
		Culverts				
		Ditches				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.
 1. Location and access road show signs of lack of stabilization/compaction
 2. Evidence of tracking onto County Road 319 from access road and tracking from location as that there is no evidence of tracking controls as stated in the provided document (BMP's for sediment tracking controls) from the operator.

Corrective Action: **Install or repair required BMPs**

Date: 03/26/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402638431	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385047
700702472	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385039