

Inspection Photos  
Operator: Simcoe  
Facility: 067-10003  
Date: 3/29/2021



Photo 1. View of the southeastern corner facing center.



Photo 2. View of the eastern fill slope facing southward. Revegetation appears to be progressing with grasses such as western wheatgrass and crested wheatgrass. Early seral annual weeds such as tumble mustard are dense within the revegetation areas.





Photo 3. View of dense Russian thistle and plastic debris within the southeastern corner. Inset shows more Russian thistle debris that needs to be removed.





Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush , blue grama, and black sage observed in the understory.