



- Photo 1 –





- Photo 2 – View west from north side of pumping unit. Oily soil in tiretrack





- Photo 3 – View south north side of location. Northern extent of fire impact





- Photo 4 – View southeast from northwest area of location. Lobes of burnt spilled oil/water





- Photo 5 – Oily soil within spill area





- Photo 6 – Oily soil within spill area





- Photo 7 – Burnt oil residue on and in berms and remains of burned partially buried water vault





- Photo 8 – Burnt oil Oily soil within spill area





- Photo 9 – Burnt fluid line on berms





- Photo 10 – Burnt fluid line on berms





- Photo 11 – Burnt fluid line on berms





- Photo 12 – Burnt fluid line on berms, fluid appears to have overtopped northwest berm area and spread on location





- Photo 13 – Burnt fluid line on berms, fluid appears to have overtopped northwest berm area and spread on location