

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2021

Submitted Date:

03/26/2021

Document Number:

699103302**FIELD INSPECTION FORM**Loc ID 434790 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Frishmuth, Rusty		rfrishmuth@hpres.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
Morgan, John		john.morgan@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434789	WELL	TA	07/02/2019	DSPW	123-38343	Anschutz State 5-62-36-12 SWD	TA

General Comment:[This was a witness on an MIT. No tubing in well.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434789 Type: WELL API Number: 123-38343 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A Well MIT no tubing in well:
 MIRU Fluid Energy Services truck, Pressured casing to 340 psig and isolated well bore from truck. Initial Casing @ 340 psig, Initial BH @0 psig. 5 Min Casing @340 psig, 5 min BH @0 psig, 10 Min Casing @340 psig, 10 min BH @0 psig, 15 Min Casing @340 psig, 15 min BH @0 psig. Released pressure, SIW. An extra 4 min. was marked due to the marker not marking on the chart.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to have no bradenhead test on file perform test and submit reports.

05/07/2021

Corrective Action: Comply with Rule 419.b

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 3/25/21 at approximately 1500hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Anschutz State 5-62-36-12 SWD of HighPoint Operating Corp., at</p> <p>API # 05-123-38343 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issue was observed:</p> <p>Appears to have no bradenhead test on file perform test and submit reports. Comply with Rule 419.b. With a corrective action date of 5/7/21.</p> <p>At the time of inspection an MIT was performed.</p> <p>T/A Well MIT no tubing in well:</p> <p>MIRU Fluid Energy Services truck, Pressured casing to 340 psig and isolated well bore from truck. Initial Casing @ 340 psig, Initial BH @0 psig. 5 Min Casing @340 psig, 5 min BH @0 psig, 10 Min Casing @340 psig, 10 min BH @0 psig, 15 Min Casing @340 psig, 15 min BH @0 psig. Released pressure, SIW. An extra 4 min. was marked due to the marker not marking on the chart.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/26/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402640502	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5386637
699103303	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5386636