

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2021

Submitted Date:

03/26/2021

Document Number:

701101320

FIELD INSPECTION FORMLoc ID 322450 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Byers, Jim		jbyers@blm.gov	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	Fruita
Jordan, Reid		maralextechjr@gmail.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113496	PIT		09/30/1980		-	W.T. SPEARS #1-28DF	
210532	WELL	SI	05/01/2012	GW	045-06288	USA 1-28DF	SI

General Comment:

This is a summary of inspection report performed by Mike Longworth at MARALEX RESOURCES INC, USA-67S99W 28SENW, Location # 322450

During this inspection the following possible compliance issues were observed:

No current MIT on record or delinquent as required by Rule 326

No label on tank. Berm not maintained.

Unused open ended risers. Burned vegetation and weeds from Pine Gulch Fire.

Fence post were burned up in Pine Gulch Fire.

Bradenhead inaccessible or not visible.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:	Location accessed via private ranch.		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No label on tank. Berm not maintained.		
Corrective Action:	Install sign to comply with rule 210.	Date:	07/01/2016

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Burned vegetation and weeds from Pine Gulch Fire.		
Corrective Action:	Comply with Rule 603.f	Date:	07/01/2016
Type	UNUSED EQUIPMENT		
Comment:	Unused open ended risers		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105. Comply with Rule 603.f	Date:	05/01/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Fence post were burned up in Pine Gulch Fire.		
Corrective Action:	Repair fence.	Date:	04/10/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	Bradenhead inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 04/07/2021
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	<50 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Containment berm is not maintained.			
Corrective Action:	Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.			Date: 04/15/2019

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: NOPit ID: 113496Lat: 39.419097Long: -108.449836Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: InadequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: YESComment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402641116	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387152
701101329	Inspection 701101320 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387150