

# Inspection Photos

3/31/2021

Operator: SG INTERESTS I LTD # 77330

Location ID: 418697

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 1:** Photos 1-3 taken from the northeast corner of the Location. Photos provide an overview of the Location from south, southwest to west.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 4:** Photo taken from the northeast corner of the Location, facing southwest. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 5:** Photo taken from the northeast corner of the Location, facing southwest. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident. 6 foot measuring stick for reference.

## Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



**Photo 6:** Photo taken from the northeast corner of the Location, at the toe of the cut slope, facing northwest. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 7:** Photo taken from the northeast end of the Location, facing southeast. Photo shows cut slopes observed in photos 4-6. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 8:** Photo taken from the slopes on the north end of the Location. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 9:** Continued from photo 8. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 10:** Photos 10-12 taken from the northwestern area of the Location. Photos provide an overview of the Location from east, south to west. Photos also show control measures to protect and stabilize the Location remain missing or insufficient.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 11:** See comments under photo 10.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 12:** See comments under photo 10.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 13:** Photo taken from the west end of the Location. Photo shows the stormwater ditch has not been constructed in accordance with good engineering practices; ditch filled with sediment.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 14:** Photo taken from the northwestern end of the Location, facing southwest. Photo shows stormwater ditch BMPs have not been constructed in accordance with good engineering practices, including an appropriate outlet to allow for sediment laden-free stormwater discharge; erosion degradation evident.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 15:** Photo taken from the western end of the Location, facing east. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; ditch has filled with sediment; erosion degradation evident; off-site sediment transport evident. 6 foot measuring stick used for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 16:** Photo taken from the western areas of the Location, facing west. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; ditch has filled with sediment; erosion degradation evident; off-site sediment transport evident. 6 foot measuring stick used for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 17:** Photo taken from the stormwater ditch on the southwest corner of the pad. Photo shows stormwater ditch BMP has not been constructed in accordance with good engineering practices, including an appropriate outlet to allow for sediment laden-free stormwater discharge.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 18:** Photo taken from the slopes below the end of the ditch observed in photo 17. Photo shows an appropriate outlet to allow for sediment laden-free stormwater discharge has not been constructed at the ditch in accordance with good engineering practices. Photo also shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation and off-site sediment transport evident.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 19:** Photo taken from the irrigation ditch on the southwestern end of the Location. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; photo also shows sediment has been discharged from the location, has filled the irrigation ditch and transported off-site. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 20:** Photo taken from the southwest of the Location, facing northeast. Photo shows control measures to protect and stabilize the Location remain missing or insufficient; erosion degradation evident; photo also shows sediment has filled an irrigation ditch, and has been transported off-site. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 21:** Photo shows off-site sediment discharge on the southwest end of the Location. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 22:** Photo shows off-site sediment discharge on the southwest end of the Location, facing west. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 23:** Photo taken from the south end of the Location, facing southeast. Photo shows erosion degradation due to runoff from the Location is now evident on the southern fill slopes. 6 foot measuring stick for reference.

Inspection Photos  
Operator Name: SG INTERESTS I LTD # 77330  
Location ID: 418697



**Photo 24:** Continued from photo 23. Photo shows off-site sediment transport and deposition.