

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 1 – Wall of Brantner Irrigation ditch during 4/1/2021 inspection; work to reconstruct wall had begun since previous inspection. Work appear to still be in progress.**

**Photo 2 – Ditch wall. Fencing around open excavation has been removed.**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 3 – Irrigation ditch floor has been scraped by excavator since last inspection.**

**Photo 4 – Collapsed wall of Brantner Irrigation ditch with scraped portions of ditch floor.**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



Colorado Oil and Gas Conservation Commission  
40.07504, -104.85432, 4904.3ft, 241°  
04/01/2021 12:10:18 PM



Colorado Oil and Gas Conservation Commission  
40.07504, -104.85432, 4910.9ft, 150°  
04/01/2021 11:21:36 AM

**Photo 5 – Clean fill on location. One soil stockpile appears to have been pushed back into open excavation.**

**Photo 6 – Soil stockpile pushed back into open excavation.**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



Colorado Oil and Gas Conservation Commission  
40.07493, -104.85448, 4906.2ft, 36°  
04/01/2021 11:38:30 AM

**Photo 7 – Soil stockpile pushed back into open excavation.**



Colorado Oil and Gas Conservation Commission  
40.07495, -104.85446, 4909.6ft, 34°  
04/01/2021 11:37:18 AM

**Photo 8 – Trash visible in open excavation**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 9 – Groundwater with hydrocarbon sheen observed in open excavation.**



**Photo 10 – Groundwater with hydrocarbon sheen observed in open excavation.**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 11 – Soils stored on location; BMPs inadequate to contain runoff**



**Photo 12 – Soils stored on location; BMPs inadequate to contain runoff**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 13 –BMPs inadequate to contain runoff; any runoff from the eastern portion of the soils stockpile would go into irrigation ditch.**

**Photo 14 – BMPs inadequate to contain runoff**

**Inspection Photos**  
**Location Name: Robert G Berge #2**  
**Spill ID 476918 (CL)/ Remediation Project No. 15743**



**Photo 15 – Vehicle tracking has extended an additional ~150’ west of the excavation, making ruts in field**

**Photo 16 – Vehicle tracking has extended an additional ~150’ west of the excavation, making ruts in field**