

**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 1 – Free product observed on groundwater in open excavation.**



**Photo 2 – Free product observed on groundwater in open excavation. Fencing down around open excavation.**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 3 – Soils stored on site with inadequate BMPs**



**Photo 4 – Soils stored on site with inadequate BMPs**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 5 –Inadequate BMPs**



**Photo 6 – Soils stored on site with inadequate BMPs**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 7 – Stained soils visible on surface.**



**Photo 8 – Stained soils visible on surface.**