

Inspection Photos
Operator: Simcoe
Facility: 067-07296
Date: 4/1/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing, largely with smooth brome and sand dropseed.



Photo 3. View of the western project area from the northwestern corner facing southward.




Photo 4. View of silt fence downslope from pipeline disturbance. Silt fence is not functioning because it is not trenched in and is blown down in portions (see inset).



Photo 5. View of the reference area comprised of irrigated grass field, cottonwood trees, and ponderosa pines.