

Inspection Photos
Operator: Simcoe
Facility: 067-08355
Date: 4/1/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with smooth brome, sand dropseed, and western wheatgrass.



Photo 3. View of velocity checks placed along the access road. These checks are not properly sized/installed as stormwater flows around the checks resulting in continued erosion along the roadside.



Photo 4. View of velocity checks at the bottom of the slope that are full of sediment and overflowing. These need maintenance.



Photo 5. View of the reference area comprised of ponderosa pine woodland with understory of gambel oak and grasses such as western wheatgrass, muttongrass, and forbs such as Oregon grape and white sagebrush.