

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/06/2021

Document Number:

690102357

FIELD INSPECTION FORMLoc ID 333225 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	
Knop, Max		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239679	WELL	PR	07/01/2019	OW	123-07467	CAMENISCH 1	EG

General Comment:

COGCC engineering integrity inspection performed on April 1st, 2021 in response to initial form 19 spill report Doc #402644033 received on 03/30/2021 that outlines: Lease operator observed surface soil staining in the vicinity of a buried flowline. Associated flowline was immediately shut in. Details regarding the flowline release are unknown until excavation activities can expose flowline.

Corrective Actions identified during this field inspection are outlined in the flowline section of report. Photos uploaded.

Inspected Facilities

Facility ID: 239679 Type: WELL API Number: 123-07467 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: COGCC Integrity Inspection performed on 1/21/2021; No KPK personnel were on location at time of field inspection. The Camenisch #1 well was observed shut in at wellhead (No OOSLAT/ tagout). Stained soils on the ground surface from the off location flowline release were observed; No initial spill response/ cleanup has been performed. The release is located approximately 500' SW of the wellhead; 150' N of battery (40.073490, -104.866545). Excavation work to expose the failed flowline has not been initiated; remediation work and flowline repairs are pending.

Corrective Action: Provide information requested below to COGCC Integrity Inspector (via email) and add to Corrective Actions section of COGCC supplemental form 19 spill report (pertaining to compliance of COGCC series 1100 flowline regulations):
 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/ operator determination)
 2) Measures taken to prevent a recurrence of failure (1102.l Corrosion Control)
 3) Description of flowline repair/replacement work completed (1102.j. Repair)
 4) Perform flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning well to service (1102.j.4 and 1102.O). Contact COGCC Integrity Inspector with schedule of repair work and pressure testing. Upload flowline pressure testing chart/ data to COGCC Form 19 subsequent.
 5) Ensure OOSLAT (valves tagged out) in place to prevent unintentional release per 1102.j.7 (prior to and during time of repair).

Date: 05/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102365	Signage and well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395955
690102366	Stained soils on surface; View S to facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395956
690102367	Flowline release; View NE to well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395957