

Inspection Photos
Location Name: RMF CO 15-09
Location ID: 330987



Photo 1 WH

Photo 2 Meter house

Inspection Photos
Location Name: RMF CO 15-09
Location ID: 330987



Colorado Oil and Gas Conservation Commission
40.05874, -104.89232, 1514.8m
Apr 7, 2021 10:12:42



Colorado Oil and Gas Conservation Commission
40.05844, -104.8923, 1515.1m
Apr 7, 2021 10:13:24

Photo 3 production equipment

Photo 4 TNK BTRY

Inspection Photos
Location Name: RMF CO 15-09
Location ID: 330987



Photo 5 mechanical issue no bull plug and stained soil under unsecured valve on produced water tank



Photo 6 mechanical issue fittings and valves leaking on load out lines on crude oil tanks

Inspection Photos
Location Name: RMF CO 15-09
Location ID: 330987



Colorado Oil and Gas Conservation Commission
40.05864, -104.89224, 1518.4m
Apr 7, 2021 10:14:26

Photo 7 Mechanical issue and stained soil on load out lines on crude oil tanks.



Colorado Oil and Gas Conservation Commission
40.05887, -104.89233, 1515.5m
Apr 7, 2021 10:15:30

Photo 8 Mechanical issue and stained soil on piping inside HOZ Sep.

Inspection Photos
Location Name: RMF CO 15-09
Location ID: 330987



Photo 9 Deep ruts on access road, road in need of proper BMP's

Photo 10 Deep ruts on access road, road in need of proper BMP's