

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2021

Submitted Date:

04/07/2021

Document Number:

699802880

**FIELD INSPECTION FORM**Loc ID 334114 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293844	WELL	PR	12/04/2007	GW	045-15137	SPECIALTY RESTAURANTS SG 11-35	PR
293853	WELL	PR	12/05/2007	GW	045-15138	SPECIALTY RESTAURANTS SG 21-35	PR
293854	WELL	PR	12/05/2007	GW	045-15139	SPECIALTY RESTAURANTS SG 321-35	PR
293855	WELL	PR	12/05/2007	GW	045-15140	SPECIALTY RESTAURANTS SG 421-35	PR
293856	WELL	PR	12/05/2007	GW	045-15141	SPECIALTY RESTAURANTS SG 521-35	PR
293857	WELL	PR	12/05/2007	GW	045-15142	SPECIALTY RESTAURANTS SG 311-35	PR
293858	WELL	PR	12/05/2007	GW	045-15143	SPECIALTY RESTAURANTS SG 411-35	PR
293859	WELL	PR	05/31/2008	GW	045-15144	SPECIALTY RESTAURANTS SG 511-35	PR

**General Comment:**

COGCC Inspection Report Summary

On Wednesday 4/7/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted, a follow up inspection at TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS-67S96W /35NWNW, Location #334114 in Garfield County Colorado.

Refer to document #699802401 inspection conducted on 1/12/21. All previous corrective actions have been completed. While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

1) Location lacks stabilization. See photo #3394 and #3395. No form of tracking control at entrance to location. See photo #3396 with a corrective action date of 4/22/21.

- Location is located on the edge of a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 8		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293844	Type:	WELL	API Number:	045-15137	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293853	Type:	WELL	API Number:	045-15138	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293854	Type:	WELL	API Number:	045-15139	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293855	Type:	WELL	API Number:	045-15140	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293856	Type:	WELL	API Number:	045-15141	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293857	Type:	WELL	API Number:	045-15142	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293858	Type:	WELL	API Number:	045-15143	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293859	Type:	WELL	API Number:	045-15144	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
Gravel						
Berms						
		Ditches				
Ditches						
Other	Fail					No form of tracking control
		Gravel				
Compaction	Fail					Location lacks stabilization.
		Berms				

Comment: [Location lacks stabilization. See photo #3394 and #3395. No form of tracking control at entrance to location. See photo #3396](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 04/22/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for corrective actions.</a>	depaoloc	04/07/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802881	Photos for Insp. #699802880	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397957">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397957</a>