

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/09/2021

Document Number:

700300127

FIELD INSPECTION FORMLoc ID 325092 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 31250

Name of Operator: FRITZ & DIGMAN INC

Address: PO BOX 70024

City: ALBUQUERQUE State: NM Zip: 87197-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		vanessa@walsheng.net	
Digman, Bernie	575-640-1867	berniekdigman@gmail.com	
		vern@walsheng.net	
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213982	WELL	PR	02/01/2020	OW	067-05264	GRIFFITH, DELLA 1	SI

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	lube oil container stored on ground within pumping unit skid beams without spill prevention, several loose valves/fittings that appear no longer usable without service or repair.		
Corrective Action:	remove or stroe with adequate spill prention BMPs (note: less lube oil is used when gearbox seals are maintained).		Date: 04/19/2021
Type	OTHER		
Comment:	gear box leak appears to mixing with other release		
Corrective Action:	increase repair schedule or employ self inspection/mitigation BMPs per Rule 1002.f(2)		Date: 04/19/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	crude oil and E&P wastes and some gearbox oil around wellhead and pumping unit		
Corrective Action:	clean up without covering up free product and impacted material and dispse of in approved manner. File spill report if determined more than 1 bbl released.		Date: 04/09/2021

In Containment: No

Comment: A white powder spill response material appears to have been used on portions of spill.

On site remediation requires a pre-approved Form 27 per 905.e(2)

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	gas line to combustor disconnected both ends		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	~1" riser near wellhead, unclear if plumbed bradenhead or flowline based on visual surface inspection.		
Corrective Action:	confirm bradenhead is readily accessible for monthly monitoring and annual testing, provide monthly monitoring results per 419.a(1) and 419.b(5)		Date: 04/19/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	~1' x 2' oil stain inside containment across from bottom tank valve			
Corrective Action:	clean up impacted			Date: 04/19/2021

Venting:

Yes/No	NO
Comment:	shut in at time of inspection, combustor on site, flowline disconnected.
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	213982	Type:	WELL	API Number:	067-05264	Status:	PR	Insp. Status:	SI

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Compaction				
		Gravel				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: _____

Current Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM

Equipment

Oil Tank(s)

Wellhead(s)

Comment: no FLIR detectable leaks at wellhead, thief hatch or tank seals

Corrective

Date:

Action:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300128	wellhead area, spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399670
700300129	pump jack skid, gearbox leak and spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399671