

Construction and Stormwater Inspection

April 7, 2021

Operator: GMT EXPLORATION COMPANY LLC- #10243

Location ID: 478811

Inspection Document #: 697502759

Elbert County, CO

SENW Section 10 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 1. Photo taken from the southern location, facing East. Photo illustrates the Operator has installed a ditch and berm BMP during construction operations. However, the BMP is not in proper functioning condition.

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 2. Photo taken from the southeastern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 3. Photo taken from the southeastern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 4. Photo taken from the northern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 5. Photo taken from the northwestern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 6. Photo taken from the western location, facing South. Photo illustrates the Operator has sufficiently stabilized the berm BMP.

Note- topsoil has been salvaged and stored along the western perimeter of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502759

Inspection Photos
Location Name: Vulcan /6-64 10-8 Pad
Location ID: 478811



Photo 7. Photo taken from the northern location, facing Southwest. Photo illustrates the Operator appears to have salvaged topsoil in compliance with Rule 1002.b. There was an observed color change from topsoil to subsoil.

