

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/09/2021

Submitted Date:

04/12/2021

Document Number:

701500286

FIELD INSPECTION FORM
 Loc ID 335962 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

21 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jes	832-624-0810	jessica.dooling@exxonmobile.com	Lead regulatory coordinator
Thompson, Bud		BLThomps@BLM.gov	
Clark, Erin	405-319-3250	erin.k.clark@exxonmobile.com	Lead regulatory coordinator
Sutton, Derek		derek_sutton@xtoenergy.com	Area foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294503	WELL	PR	01/01/2021	GW	103-11180	PICEANCE CREEK UNIT 197-36A1	PR
294504	WELL	PR	10/27/2011	GW	103-11181	PICEANCE CREEK UNIT 197-36A2	PR
294505	WELL	PR	07/01/2015	GW	103-11182	PICEANCE CREEK UNIT 197-36A3	PR
294506	WELL	PR	12/01/2020	GW	103-11183	PICEANCE CREEK UNIT 197-36A4	PR
294507	WELL	PR	07/01/2017	GW	103-11184	PICEANCE CREEK UNIT 197-36A5	PR
294508	WELL	PR	11/01/2020	GW	103-11185	PICEANCE CREEK UNIT 197-36A6	PR
294509	WELL	PR	12/01/2020	GW	103-11186	PICEANCE CREEK UNIT 197-36A7	PR
294510	WELL	PR	12/15/2011	GW	103-11187	PICEANCE CREEK UNIT 197-36A8	PR
294511	WELL	PR	04/01/2020	GW	103-11188	PICEANCE CREEK UNIT 197-36A9	PR
294512	WELL	PR	05/01/2012	GW	103-11189	PICEANCE CREEK UNIT 197-36A10	PR

General Comment:

A routine inspection identified the following compliance issues:

- 1) Compaction incomplete on location. Photos 5 & 6. Complete by 6-12-2021.

Note: A gas leak was occurring at well 197-36A6. The operator was contacted and the leak was fixed in <30 minutes by greasing the valve.

Location is within a Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, Rule 1202.d Elk winter concentration area, and a Black bear area.

This is a summary of inspection report 701500286.

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign at location entrance.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	Well manifold, communication building, and 2 pump trailers.		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical containers.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:	Tank on skid. The inspector was uncertain if the tank is for produced water or injected fresh water.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Plastic under tank. No berm present.				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	294503	Type:	WELL	API Number:	103-11180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294504	Type:	WELL	API Number:	103-11181	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294505	Type:	WELL	API Number:	103-11182	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294506	Type:	WELL	API Number:	103-11183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294507	Type:	WELL	API Number:	103-11184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294508	Type:	WELL	API Number:	103-11185	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294509	Type:	WELL	API Number:	103-11186	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	294510	Type:	WELL	API Number:	103-11187	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	294511	Type:	WELL	API Number:	103-11188	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID:	294512	Type:	WELL	API Number:	103-11189	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel		Material Handling And Spill Prevention		
Berms						
Culverts						
Ditches						
Retention Ponds						
Rip Rap						

Comment: [Cattle guard across location entrance. Tracking on location near wells.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/12/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	294701	1433808	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500287	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400391