

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 well head and pump jack.



Nielson #3 location photo with tank battery in the background.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Oil stained well head.



Nielson #3 tank battery.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Drip pot of south AST.



Anchors have been installed, but are not connected to the tanks.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Northern AST has oil staining the side.

Oil stained soil at the base of the northern AST.