

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/12/2021

Submitted Date:

04/12/2021

Document Number:

699103376

FIELD INSPECTION FORM
 Loc ID 429920 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections
Ashby, Andrew		AAshby@bonanzacrk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429920	LOCATION	AC			-	North Platte P-T-34HZ Pad	AC

General Comment:

This is a follow up to FIRR #402639602. CA's not approved, did not meet expectations. This is an inspection on the Archrock compressor.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil next to compressor needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: <u>04/02/2021</u>
Type	OTHER		
Comment:	Oily waste on compressor skid needs to be removed. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: <u>04/02/2021</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	Appear to have multiple leaking valves/ fittings on compressor causing oily waste on skid needs to be fixed or replaced. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>04/02/2021</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 429920 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 4/12/21 at approximately 1300hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR #402639602 at North Platte P-T-34HZ Compressor Location of Bonanza Creek Energy, at Facility ID # 429920 in Weld County, Colorado.</p> <p>CA's were not corrected, they did not meet expectations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Appear to have multiple leaking valves/ fittings on compressor causing oily waste on skid needs to be fixed or replaced. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 4/2/21.</p> <p>Oily waste on the compressor, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 4/2/21</p> <p>Stained soil next to compressor needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 4/2/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	04/12/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103377	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401100