

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2021

Submitted Date:

04/06/2021

Document Number:

696303113

**FIELD INSPECTION FORM**

Loc ID 327437 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10391  
Name of Operator: STONEHAM PRODUCTION LLC  
Address: 5945 ZINNIA COURT  
City: ARVADA State: CO Zip: 80004

**Findings:**

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbarton@sterlingenergy.us	<a href="#">Sterling Energy</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246899	WELL	PR	08/01/2019	GW	123-14696	CRAIG 2	PR

**General Comment:**

[Follow-Up Inspection to FIR 696302393 dated 09.01.2020](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at Gas Engine, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."		Date: <u>04/21/2021</u>
Type	STORAGE OF SUPL		
Comment:	Unused Pipe in NE Corner of Location, see photos		
Corrective Action:	Comply with Rule 606		Date: <u>05/07/2021</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	#		
Comment:	Gas Meter Calibration is now up to date		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		

Comment:	Appears to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.718610,-103.663070
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No		Date:
Comment:		
Corrective Action:		

**Flaring:**

Type		Date:
Comment:		
Corrective Action:		

**Inspected Facilities**

Facility ID: 246899 Type: WELL API Number: 123-14696 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 10/14/2019 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: TSTM

Comment: Annual Bradenhead Test is overdue.

05/07/2021

Corrective Action: Complete Annual Bradenhead Test per Rule 419.c

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Drains				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective

Date:

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective

Date:

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective

Date:

**Fencing:**

Fencing Type:      Fencing Condition:

Comment:

Corrective

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date:

Type: Produced Water Lined: NO Pit ID: Lat: 40.718470 Long: -103.662640

Reference Point: SE Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective

Date:

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a></p> <p>On Thursday 04/01/2021 at approximately 11:46, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Stoneham Production LLC, Craig #2, Location #327437 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Stained Soil at Gas Engine. See photos. Corrective Action Date 04.21.2021</p> <p>Unused Pipe on the Northeast Corner of location. See photos. Corrective Action Date 05.07.2021</p> <p>Bradenhead Annual Test is overdue. Complete Bradenhead Test on Form 17 per Rule 419.c. Corrective Action Date 05.07.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	04/06/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402650189	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395969">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395969</a>
696303114	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5395961</a>