

# Inspection Photos

API: 071-06814

Operator: WAPITI OPERATING LLC

Inspection Date: 4/12/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06814 | Date: 4/12/2021

## Inspection Photos



**Photo 1.** Facing toward the access road and location which appears to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06814 | Date: 4/12/2021

## Inspection Photos



**Photo 2.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06814 | Date: 4/12/2021

## Inspection Photos



**Photo 3.** There is signs of produced water discharge from this pipe. There is a grey/brown in area circled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06814 | Date: 4/12/2021

## Inspection Photos



**Photo 4.** There is signs of discharged which flowed down hill from the pipe outlet (red arrow).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06814 | Date: 4/12/2021