

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/05/2021

Submitted Date:

04/07/2021

Document Number:

693802919**FIELD INSPECTION FORM**Loc ID 322429 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		regulatory@foundationenergy.com	All inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
119495	PIT	AC	03/27/2017		-	Federal #3-11-8-104 119495	AC
210481	WELL	SI	06/01/2020	GW	045-06237	FEDERAL 3-11-8-104	SI

General Comment:

COGCC staff performed a routine field inspection on 12/17/2020.
Issues were found requiring corrective action. See inspection text and photos for details.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Chemical injector next to separator has no readable contents or NFPA labels.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/05/2021
Type	WELLHEAD		
Comment:	Sign on separator fence at location entrance.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	1-866-767-3600 or 911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	TRASH		
Comment:	Trash inside produced water tank berms		
Corrective Action:	Comply with Rule 606	Date:	04/16/2021
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hogwire & T-post around separator, meter housings and blowdown pit.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hogwire & T-post around Pump jack and produced water tank		
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		39.381611,-108.963760
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 119495 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 210481 Type: WELL API Number: 045-06237 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well shut in 6/1/2020.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment of chemicals.

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NOPit ID: 119495Lat: 39.381543Long: -108.964161Reference Point: SEOther: Length: 20Width: 20**Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402652160	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397570
693802931	Inspection photos 4/5/2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397565