

Inspection Photos
Location Name: F.S. Duncan B 3
Location ID: 312843



Photo 1. Overview of location taken facing northwest.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: F.S. Duncan B 3
Location ID: 312843



Photo 3. Stained soil at separator.



Photo 4. Incomplete tank labels.



Inspection Photos
Location Name: F.S. Duncan B 3
Location ID: 312843



Photo 5. Erosion rills transporting sediment off location.



Photo 6. Erosion rills transporting sediment off location.



Inspection Photos
Location Name: F.S. Duncan B 3
Location ID: 312843



Photo 7. Erosion rills transporting sediment off location.



Photo 8. Erosion rills transporting sediment off location.

