

Inspection Photos

API: 071-06141

Operator: OGRIS OPERATING LLC

Inspection Date: 4/14/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021

Inspection Photos



Photo 1. The culvert in the main canyon is filled in with debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021

Inspection Photos



Photo 2. There are vehicle ruts along areas of th road which need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021

Inspection Photos



Photo 3. There is vehicle rutting along the first switch back in the road. It appears vehicles are spinning out in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021

Inspection Photos



Photo 4. At the second switch back in the road, stormwater diverted off the road has caused erosion in bottom right of photo. This area needs to be stabilized with BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06141 | Date: 4/14/2021