

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/14/2021

Submitted Date:

04/15/2021

Document Number:

701500336

**FIELD INSPECTION FORM**Loc ID 316271 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260089	WELL	SI	10/01/2020	GW	103-10132	WRD DOW 20-11	SI

**General Comment:**

A follow up inspection of documents:  
1 FIR 700702064 dated 12-28-2020.

The following compliance issues are uncompleted:  
1) Paraffin wax under separator. Photo 8. Complete by 2-2-2021.

Additional compliance issues:  
1) Stabilization not complete on location. Photo 10. Complete by 6-15-2021.  
2) Debris on location. Photos 2, 4, 9. Complete by 4-30-2021.  
3) Gaps in tank secondary containment. Photos 5 & 6. Complete by 5-15-2021  
4) Stained soil at oil tank. Photo 8. Complete by 5-15-2021.  
5) Battery sign not present. Photos 1 & 11. Complete by 6-15-2021.  
6) Production history not current.

Location is within a Rule 1202.c Aquatic sportfish management area, Rule 1202.d Mule deer severe winter range area, and Rule 1202.d Mule deer winter concentration area.

This is a summary of inspection report 701500336.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No battery sign present.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 06/15/2021
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment: 800-209-9762

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at oil tank.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.		Date: 05/15/2021
Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.		Date: 04/30/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead access present.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment: <a href="#">Chemical container.</a>		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment: <a href="#">Paraffin under separator.</a>		Date:
Corrective Action: <a href="#">remove stained soil under separator/repair any potential mechanical issues that is causing leaking paraffin</a>		Date: <a href="#">02/01/2021</a>
Type: Plunger Lift	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Inspector Name: Moran, Rick

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal				Inadequate	
Comment:	Gaps in metal secondary containment connections.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	05/15/2021

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 260089 Type: WELL API Number: 103-10132 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production June 2020. Report pastdue monthly operations.

Submit required Form 7(s) to COGCC per rule 413.b.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical secondary containment.
Compaction	Fail					
Gravel		Gravel				

Comment: Compaction of location is not complete.Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.Date: 05/15/2021Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500337	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405085">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405085</a>