

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/09/2021

Document Number:

696303121

FIELD INSPECTION FORMLoc ID 438327 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Boyd, William		wboyd@pedevco.com	All Inspections
Binschus, Chris		chris.binschus@state.co.us	
Allison, Rick		rick.allison@state.co.us	
Shepard, DeAnn		dshepard@pedevco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438322	WELL	PR	07/01/2020	OW	123-39927	Loomis 2-3H	PR
438324	WELL	PR	12/31/2014	OW	123-39929	Loomis 2-6H	PR
438325	WELL	PR	12/01/2020	OW	123-39930	Loomis 2-1H	PR

General Comment:

Follow-Up Inspection to FIR 696302946 dated 02.09.2021 and FIR 696302736 dated 12.07.2020. This is a Follow-Up Field Inspection. Any corrective action(s) from previous Intertim Reclamation and Stormwater Inspections that have not been addressed are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Wells and Compressor, ECD and Flare, East Treater. See photos Flare - Stained Soil went off location and into Pasture to the East. See photos Corrective Action Date remains the SAME at 02.12.2021		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	02/12/2021
Type	WEEDS		
Comment:	Weeds in Interim Reclamation Area - See photos and refer to FIR 682504486 dated 02.04.2019		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flare	# 1		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Day Tank at West Pumping Unit missing Wildlife Netting, see photos		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 04/30/2021
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Gas Lift Injection Wellhead		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Day Tank Netting is in disrepair, see photos		
Corrective Action:	Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b.		Date: 04/30/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	9	400 BBLs	STEEL AST		40.597560,-104.061800	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type	Field Flare					
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 438322	Type: WELL	API Number: 123-39927	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 438324	Type: WELL	API Number: 123-39929	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	
Facility ID: 438325	Type: WELL	API Number: 123-39930	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 04/07/2021 at approximately 13:07, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum LLC, Loomis 2-1H PAD, Location #438327 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Stained Soil at Wells, Gas Engines/Exhaust, Compressor, ECD and Flare, East Treater. See photos. Flare - Stained Soil went off location and into Pasture to the East. See photos. Corrective Action Date remains the SAME at 02.12.2021</p> <p>Day Tank at West Pumping Unit is missing Wildlife Netting. Compressor Day Tank Netting is in disrepair, see photos. Corrective Action Date at 04.30.2021</p> <p>Weeds in Interim Reclamation Area - See photos and refer to FIR 682504486 dated 02.04.2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	04/09/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402654155	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399547
696303122	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399545