

TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884



**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWE
Location # 323884**



Unused piece of poly pipe along poly water moving pipe.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWE
Location # 323884**



Inlet basin of culvert needs cleaned out.



Culvert is damaged in road side ditch.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Culvert outlet needs cleaned.



Storm water washing bank at culvert outlet.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Road ditch needs maintained.

TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884



Water crossing roadway and over bank of road.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



**Storm washing and damaging roadside bank from
storm water crossing roadway.**

TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884



Storm water ditch running towards location.



Sediment build up over vegetation.

**TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884**



Storm water damage on perimeter ditch around location.

TEP ROCKY MOUNTAIN LLC
UNOCAL-67S96W 2NWNE
Location # 323884

