

Inspection Photos
Operator: Hilcorp
API: 067-09426
Date: 4/15/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southwestern corner facing northward. Revegetation is established here and largely continuous with surrounding grass crop field.



Photo 3. View of the western project area from the southwestern corner facing northward. This area is comprised of dense kochia and is not in cultivation. Revegetation needs to be conducted here.



Photo 4. View of the reference area east of the well pad, facing westward. Vegetation is comprised of irrigated grass field.



Photo 5. View of closed gate after leaving location.