

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2021

Submitted Date:

04/19/2021

Document Number:

701500374

FIELD INSPECTION FORMLoc ID 315379 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Boulger, Levin		lboulger@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230739	WELL	PR	11/08/2000	GW	103-08408	CONTINENTAL 4-28	SI

General Comment:

A follow up inspection of documents:

- 1) FIR 700404694 dated 12-22-2020.

The following compliance issues were resolved:

- 1) The emergency phone number is answered.

The following compliance issues are uncompleted:

- 1) Report past due monthly operations on Form 7.
- 2) Provide bradenhead access. Photo 3. Complete by 2-1-2021.
- 3) Calibrate gas meter. Photo 4. Complete by 2-1-2021.

Location is within a Rule 1202.c Aquatic sportfish management area, Rule 1202.d Mule deer migration corridor, Rule 1202.d Elk winter concentration area, and a Black bear area.

This is a summary of inspection report 701500374.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: Bradenhead access is not present.			
Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 02/01/2021	
Type: Gas Meter Run	# 1		
Comment: Most recent meter calibration in June 2019.			
Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 02/01/2021	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	40 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment: No berm present. Top of tank below adjacent ground level.				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 230739 Type: WELL API Number: 103-08408 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last reported production in May 2020. No audible gas flow. Report past due monthly operations.

Submit required Form 7(s) to COGCC per rule 413.b.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other						Native vegetation on location.

Comment: [No significant soil migration; erosion or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500375	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5406924