

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/07/2021

Submitted Date:

04/10/2021

Document Number:

692403282**FIELD INSPECTION FORM**
 Loc ID 334668 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211444	WELL	PR	06/14/2002	GW	045-07204	SCARBER 2-42	RI
269170	WELL	PR	06/01/2019	GW	045-09324	SCARBER FEDERAL 2-13 (RN2)	RI
272868	WELL	PR	04/22/2005	GW	045-10184	SCARBER FEDERAL 2-12D (RN2)	RI
272869	WELL	SI	01/01/2020	GW	045-10183	SCARBER FEDERAL 2-14D (RN2)	RI

General Comment:

This is an Interim Reclamation focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

Inspected Facilities

Facility ID: <u>211444</u>	Type: <u>WELL</u>	API Number: <u>045-07204</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>269170</u>	Type: <u>WELL</u>	API Number: <u>045-09324</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>272868</u>	Type: <u>WELL</u>	API Number: <u>045-10184</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>272869</u>	Type: <u>WELL</u>	API Number: <u>045-10183</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment _____

BMPs have become Debris at East pad perimeter. May have been damaged during snow removal.

Corrective Action _____

Remove Debris

Date 05/12/2021

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Site appeared stable at time of Inspection.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402657089	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401901
692403292	Inspection Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401893