

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/12/2021

Submitted Date:

04/13/2021

Document Number:

696303128

FIELD INSPECTION FORM
 Loc ID 431634 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10503

Name of Operator: RED HAWK PETROLEUM LLC

Address: 575 N DAIRY ASHFORD STE 201

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|-------------------------|-----------------|
| Boyd, William | | wboyd@pedevco.com | All Inspections |
| Kraich, Adam | | adam.kraich@state.co.us | |
| Shepard, DeAnn | | dshepard@pedevco.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 431633 | WELL | PR | 02/01/2018 | OW | 123-36703 | Buchner 2-2H | PR |

General Comment:

Follow-Up Inspection to FIR 696302943 dated 02.08.2021

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Concrete Vault missing Tank Labels - NFPA, Content, and Capacity. See photos. Corrective Action Date remains the same. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 03/08/2021 |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained Soil and Mechanical Conditions STILL REMAIN at Gearbox, Gas Engine and Flare, see photos. Corrective Action Date remains the same | | |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e." Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition For localized stained soils or oily waste - Properly dispose of oily waste per Rule 608.e. | Date: | 12/23/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|-------------------------------|----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |

| | | | |
|-------------------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flare | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heater Treater | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 400 BBLs | FIBERGLASS AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | | |
| Corrective Action: | | | | | Date: |

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 3 | 400 BBLs | STEEL AST | | 40.332000,-104.067010 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| | | | |
|------------------------|----|-------|--|
| <u>Venting:</u> | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|------------------------|-------------|-------|--|
| <u>Flaring:</u> | | | |
| Type | Field Flare | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 431633 | Type: | WELL | API Number: | 123-36703 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>On Wednesday 04/07/2021 at approximately 13:01, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum LLC , Buchner 2-2H, Location #431634 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Stained Soil STILL Remain at Gearbox, Gas Engine house and Flare, see photos. Original Corrective Action Date still remains at 12.23.2020</p> <p>Concrete Vault missing Tank Labels - NFPA, Content, and Capacity. See photos. Corrective Action Date remains the same at 03.08.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p> | petrie | 04/13/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402657253 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5402002 |
| 696303129 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401996 |