

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW

Location ID: 311684



Photo #3531 from entrance to location.



Photo #3532 from entrance to location.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW

Location ID: 311684



**Photo #3533 from entrance to location.**



**Photo #3534 Location lacks stabilization.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW

Location ID: 311684



**Photo #3314 from Inspection #699802832 conducted on 3/26/21.**



**Photo #3535 Location lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW

Location ID: 311684



Photo #3315 from Inspection #699802832 conducted on 3/26/21.



Photo #3538 No form of tracking control at entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW

Location ID: 311684



Photo #3316 from Inspection #699802832 conducted on 3/26/21.



Photo #3536 Sediment has been transported off of NE end of location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW**

**Location ID: 311684**



**Photo #3537 Sediment is choking off vegetation.**

