

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402666340

Date Received:
04/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690102340
Inspection Date: 03/17/2021 FIR Submit Date: 03/22/2021 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335610

Location Name: KIEFER GEORGE W UT B-61N67W Number: 14SWSE County: _____
Qtrqtr: SWSE Sec: 14 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.045473 Longitude: -104.855309

FACILITY - API Number: 05-123-00 Facility ID: 479618

Facility Name: KIEFER GEORGE W UT B #1A Number: _____
Qtrqtr: SWSE Sec: 14 Twp: 1N Range: 67W Meridian: 6
Latitude: 40.045473 Longitude: -104.855309

CORRECTIVE ACTIONS:

1 CA# 147755

Corrective Action:

Date: 04/23/2021

Provide information requested below to COGCC Integrity Inspector (via email) and add to Corrective Actions section of COGCC supplemental form 19 spill report (pertaining to compliance of COGCC series 1100 flowline regulations):

- 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/ operator determination)
- 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control)
- 3) Description of flowline repair/replacement work completed (1102.j. Repair)
- 4) Perform flowline pressure testing to verify integrity of repairs/ reconnections completed prior to returning well to service (1102.j.4 and 1102.O). Contact COGCC Integrity Inspector with schedule of repair work and pressure testing. Upload flowline pressure testing chart/ data to COGCC Form 19 subsequent.

Response: CA COMPLETED

Date of Completion: 04/20/2021

Operator
Comment:

Supplemental Spill/Release Report #402664788 has been submitted to COGCC.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 4/21/2021 11:00:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files