

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 1. Overview of location taken facing northeast.



Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 2. Incomplete sign at location entrance.



Photo 3. Signs at entrance incomplete.



Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 4. Incomplete wellhead sign.



Photo 5. Incomplete wellhead sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 6. Incomplete wellhead sign.



Photo 7. Incomplete/inaccurate tank label.

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834

Lease # _____ County Jackson S. Co.

Stat. Range 10.84 - 250.84 ☒ PSIA ☐ PSIG

Diff. Range 0 - 250 Temp. Range 0 - 150

Temp. Base 60 Press. Base 14.73

Atmos. Press 10.84 SP TAP ☒ Upstream ☐ Downstream

Run Size 4.081 Elevation 8141' Fitting: ☐ Sr. ☒ Simplex ☐ Flange

METER INFO

Meter Make Fisher RDC 827 Sensor S/N 0484929

Meter S/N 21483565 Sensor Limits: LOW HIGH

Meter Run Make TMCO Sine Shot SP 1.5 1500

S/N 121243 DP 0 250

CB 17294.001 Temp 200 850

Model 0140104

ORIFICE PLATE			METER TEST		GAS ANALYSIS		
DATE	SIZE	INSPD BY	DATE	TESTED BY	DATE	SPEC. GRAVITY	ANALYSED BY
-	1.500	-	4/25/17	JP	4/28/17	.8873	JP
3/14/18	1.500	JP	3/15/18	JP	-	.8873	-
8/26/18	1.500	JP	8/20/18	JP	9/24/18	.8302	JP
4/10/19	1.500	JP	4/10/19	JP	11/1/19	.8767	JP
4/24/19	1.500	JP	4/24/19	JP	4/24/19	.7914	JP
-	1.500	-	-	-	4/27/19	.8130	JP
11.6.19	1.500	NPI	11.6.19	RAO			

Photo 8. Gas meter not calibrated annually.



Photo 9. Equipment stored on location.

