

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2021

Submitted Date:

04/13/2021

Document Number:

699802914

FIELD INSPECTION FORMLoc ID 311747 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454790	WELL	PR	10/01/2018	OW	077-10562	PVGP SCU 0992-18-09W	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 4/13/21 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC BCU /13A Pad, Location #311747 in Mesa County Colorado. While there, I observed normal production operations. During this inspection the following possible compliance issues were observed:

- 1) Battery sign weathered and not legible. See Photo #3467 with a corrective action date of 7/13/21.
- 2) Location lacks stabilization. See photo #3468 and #3469. No form of tracking control at entrance to location. See photo #3470 with a corrective action date of 4/28/21.

- Location is located on the edge of a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Type	TANK LABELS/PLACARDS				
Comment:					
Corrective Action:					Date:
Type	CONTAINERS				
Comment:	Chemical tank				
Corrective Action:					Date:
Type	BATTERY				
Comment:	Battery sign weathered and not legible. See Photo #3467				
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged sign. Note there is no battery sign located at the battery. The previous information was posted at the entrance to location and does not meet the new battery sign requirements of Rule 605 e.				Date: 07/13/2021
Emergency Contact Number:					
Comment:	911				
Corrective Action:					Date: _____
Good Housekeeping:					
Type	UNUSED EQUIPMENT				
Comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	LOCATION				
Comment:	Barbed wire fence around location				
Corrective Action:					Date:
Equipment:					
Type: Emission Control Device				# 1	corrective date

Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Portable compressor next to wellhead		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellhead		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	454790	Type:	WELL	API Number:	077-10562	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Compaction	Fail					Location lacks stabilization.
Ditches						
		Sediment Traps				
Berms						
Gravel						By tank battery
Sediment Traps						
Rip Rap						
		Compaction				
		Culverts				
		Gravel				
Other	Fail					No form of tracking control
Waddles						
		Ditches				

Comment: [Location lacks stabilization. See photo #3468 and #3469. No form of tracking control at entrance to location. See photo #3470.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 04/28/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Signs/Markers and storm water for corrective actions.	depaoloc	04/13/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402659628	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404103
699802915	Photos for Insp. #699802914	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404098