

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29NESE

Location ID: 322309



Photo #3565 from entrance to location.



Photo #3566 No battery sign located at the tank battery

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29NESE

Location ID: 322309



**Photo #3567 Cut slope lacks stabilization**



**Photo #3568 Cut slope lacks stabilization**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-67S95W /29NESE

Location ID: 322309



**Photo #3569 Run on to location is not being effectively controlled.**



**Photo #3570 Rocks and debris are encroaching on production equipment.**